TEXAS AVENUE CORRIDOR STUDY PROPERTY INVENTORY SURVEY FORM GROUP 3

Property ID:	R49125

Property Information

property address:	<u>407-409 PEASE</u>	
legal description:	WINTER, BLOCK 2, LOT 13 (REPI	AT OF PT OF 11&12)
owner name/address:	MISC PROPERTIES LTD	
	1507 S COLLEGE AVE	
	BRYAN, TX 77801-1214	
full business name:	1.5	
land use category:	M.E.	type of business:
current zoning:		occupancy status:
lot area (square feet):	<u> </u>	frontage along Texas Avenue (feet):
lot depth (feet):	95	sq. footage of building: 2054
property conforms to:	≝ min. lot area standards □	min. lot depth standards min. lot width standards
Improvements		,
# of buildings:	building height (feet): _	/5 # of stories:
type of buildings (spec		

building/site condition	n: <u>3</u>	
buildings conform to r	minimum building setbacks:	yes on (if no, specify)
nossible historic reson	ion date: accessible to the rce: □ yes pro sidewa	public: yes yes lks along Texas Avenue: yes yes yes (pipe fences, decks, carports, swimming pools, etc.)
Freestanding Signs		
□ yes ÇÎno		□ dilapidated □ abandoned □ in-use
# of signs:	tune/material of sign	ti unapidated ti abalidolled ti in-use
		7 20
any dhapid	ated signs suggested? yes	no (specify)
	o parking spaces striped:	yes □ no # of available off-street spaces:
		cient off-street parking for existing land use: wyes 🗆 no
overall condition:		
	ders: □ yes □ no:	

Curb Cuts on Texas Avenue
how many: curb types: □ standard curbs □ curb ramps curb cut closure(s) suggested? □ yes □ no
if yes, which ones:
meet adjacent separation requirements: yes no meet opposite separation requirements: yes no
Landscaping yes to no (if none is present) is there room for landscaping on the property? yes to no comments:
Outside Storage yes yno (specify) (Type of merchandise/material/equipment stored)
dumpsters present: □ yes □ no are dumpsters enclosed: □ yes □ no
Miscellaneous
is the property adjoined by a residential use or a residential zoning district?
yes no (circle one) residential use residential zoning district
is the property developable when required buffers are observed?
if not developable to current standards, what could help make this a developable property?
accessible to alley: yes pho
Other Comments: